

General Notes - ST-Projection Screens

The base material of all our projection screens is casted high-quality acrylic glass (PMMA) and has the same cleaning and handling specifications.

Delivery

Please note all visible packing damages immediately at the forwarder, otherwise there is no insurance. You can note transport damages at the screen which was not visible by delivery within 3 days after delivery.

Handling

ST-Projection Screens must be transported and stored upright standing or down flat. Not flat storing can deform the screen.
Useable between -40°C up to +70°C.

Installation

ST-Projection Screens have no special front or back side and are useable from both sides. Please pull off protection foils on both sides before use. Mount the screen in hanging style that no bending is possible. Easy to drill and to cut with circular saw. To glue with Acrifix for example.

Cleaning

Screens should be cleaned with clean, lukewarm water and a clean, nonabrasive, non-contaminating cloth. If desired, a mild, nonabrasive detergent may also be used. Use only light pressure when cleaning. If the surface is exceptionally dirty or gritty, "rinse" the surface first by lightly swabbing a saturated cloth over the surface and allowing surfactants to drain away. Avoid rubbing dirt or grit into the surface. Turn the cloth often and replace with a clean cloth frequently. Dry by blotting gently with a clean, dry cloth.

DO NOT USE ketones, aromatics, esters, halogens, window cleaning sprays, alcohol, kitchen scouring compounds, or solvents (such as acetone, benzene, gasoline, carbon tetrachloride, or thinners). Do not use ammonia based cleaning solutions on the acrylic as it will eat into the sheet and cause it to craze.